

Corrigendum to Report no. 1/2017 Performance Audit – Worksafe ACT’s Management of its regulatory responsibilities for the demolition of loose-fill asbestos contaminated houses

Replace existing paragraphs 3.57 and 3.58 with the following paragraphs:

- 3.57 The Audit Office reviewed a ten per cent selection of records of demolitions for 2015 and 2016. The selection indicates that the Asbestos Team received air quality monitoring results for around 60 per cent of the sites where demolition activity predominantly occurred in 2015, while no air quality monitoring results were received for the selection of sites where demolition occurred after February 2016. It was not apparent in records why air quality monitoring results were received in 2015 and not received after February 2016 and whether those collected in 2015 were reviewed.
- 3.58 The Asbestos Team received an average of 4.5 days of air quality monitoring results per site, where received, for the ten per cent selection of records. The results in the selection do not indicate that the level of 0.01 fibres / ml was breached in any instance. No action is necessary by the contractor for readings below 0.01 fibres / ml.